

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101553 dated 09/06/2025 has been generated in reference to Service order No. 147170 dated 28/05/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01507/AC 1T SIC 12TTC3 WYQ SPLIT 3S
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01507 AC 1T SIC 12TTC3 WYQ SPLIT 3S

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 250100229SA12505PZ

Invoice No : 11373027

Invoice Date : 18/02/2025

DOP : 18/02/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : RAMESH V

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI LAKSHMI FURNITURE MART SRI LAKSHMI FURNITURE M

Address : SRI LAKSHMI FURNITURE MART SRI LAKSHMI FURNITURE MART NO 220A BIG BAZAR STREET, MANNARGUDI,

City: MANNARGUDI H.O

Telephone Number : 6381420512

Mobile Number : 6381420512

Observation text: SEALED SYSTEM GAS LEAK PROBLEM DEALER REPLACED TO CUSTOMER MACHINE CUST DOP : 15/05/2025. KINDLY APPROVE SIR.

Approval remark: GAS LEAK CASE-CUST NOT ACCEPTING REPAIR. MAY DOP 2025

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.