

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101554 dated 09/06/2025 has been generated in reference to Service order No. 147407 dated 31/05/2025.

Area : SS4 COIMBATORE

Model : 40101701SD01442/AC 1.5T SIC 18TTC3 WYQ Split
***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01442 AC 1.5T SIC 18TTC3 WYQ Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 250100158SA04563ZT

Invoice No : 11020291

Invoice Date : 29/01/2025

DOP : 29/01/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : RAM & CO RAM & CO

Address : RAM & CO RAM & CO NO 18/38, SETHUPATHI NAGAR THIRUPUVANAM

City: Tiruppuvanam S.O

Telephone Number : 9092649202

Mobile Number : 9994131204

Observation text: CUSTOMER CASE-DEALER REPLACED TO CUSTOMER SEALED SYSTEM GAS LEAK. CUS DOP-28/03/2025 NO STOCK FOR RC & SRN DONE. PLS APPROVE SIR

Approval remark: SEALED SYSTEK GAS LEAK-CUST CASE MAR 2025 DOP

Sanction text: sealed system problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.