

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/W/102819 dated 09/06/2025 has been generated in reference to Service order No. 397537 dated 04/06/2025.

Area : SS4 COIMBATORE

Model : 52141601SD00506/WFEON CRS 6510 5.0 FKEDM GLWH  
\*\*\*\*\* SRN \*\*\*\*\*

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00506 WFEON CRS 6510 5.0 FKEDM GLWH

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 241000506WF00402ZK

Invoice No : 11162525

Invoice Date : 19/03/2025

DOP : 19/03/2025

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : KAVERI ELECTRONICS KAVERI ELECTRONICS

Address : KAVERI ELECTRONICS KAVERI ELECTRONICS EB OFFICE OPP KOVAI RD KAR UR-639002

City: Andankoil B.O

Telephone Number : 7845096266

Mobile Number : 9942185825

Observation text: DEFECTIVE COMPLAINT- TUB ASSEMBLT OUTER TUB LEAK DEALER RE PLACED TO CUSTOMER. CUSTOMER DOP-12/5/25 NO STOCK FOR RC & SRN DONE. PLS AP PROVE SIR

Approval remark: tub leak-cust case-not accpeting repair may 2025 dop

Sanction text: Tub assembly problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.