

Dear NMS/SRINIR

Sanction No. SS4/A/100684 dated 16/05/2023 has been generated in reference to Service order No. 397131 dated 23/04/2023.

Area : SS4 COIMBATORE

Model : 40101701SD00786/GIC 18DTC5-WVA

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD00786 GIC 18DTC5-WVA

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 220300786SA01326

Invoice No : 11096396

Invoice Date : 01/01/2023

DOP : 12/04/2022

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI MALLIGA FURNITURE SRI MALLIGA FURNITURE

Address : SRI MALLIGA FURNITURE SRI MALLIGA FURNITURE NO;2756/1;PANANGAL SAL

AI; TIRUVARUR PO;

City: Tiruvarur H.O

Telephone Number : 6384559367

Mobile Number : 9367439367

Observation text: Gas leak in ODU condensor-3-9-22 Dealer replaced to customer on approval SRN updated - No stock

Approval remark: GAS LEAK-CUST CASE-DOP SEPT 2022. CUST NOT ACCEPTING REPAIR . REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.