

Dear NMS/SRINIR

Sanction No. SS4/A/100792 dated 30/06/2023 has been generated in reference to Service order No. 404472 dated 24/06/2023.

Area : SS4 COIMBATORE

Model : 40101701SD01126/SIC 18TTC3-WWA Split

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01126 SIC 18TTC3-WWA Split

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230301126SA06060

Invoice No : 11016212

Invoice Date : 21/03/2023

DOP : 21/03/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : BHARATH ELECTRONICS APPLIANCES BHARATH ELECTRONICS

Address : BHARATH ELECTRONICS APPLIANCES BHARATH ELECTRONICS APPLIANCES NO 2
85,,VERDON TOWER,, EVN ROAD,,ERODE

City: SURAMPATTI

Telephone Number : 2260088

Mobile Number : 9965548662

Observation text: CUSTOMER CASE,DEFECTIVE COMPLAINT.SEADLED SYSTEM GAS LEAK
& CUSTOMER NOT ALLOWED TECH TO REPAIR DEALER REPLACED TO CUSTOMER- CUSTOMER
ER DOP-21/5/23

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.