

Dear NMS/SRINIR/ajayes

Sanction No. SS4/W/101854 dated 26/07/2023 has been generated in reference to Service order No. 437538 dated 18/07/2023.

Area : SS4 COIMBATORE

Model : 52141601SD00418/WTEON VLVT 70 5.0 FDTN MTBK

Replacement Product Code : 52141601SD00418 WTEON VLVT 70 5.0 FDTN MTBK

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00418 WTEON VLVT 70 5.0 FDTN MTBK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230500418FW00238

Invoice No : 11130859

Invoice Date : 12/07/2023

DOP : 12/07/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - PAINT SCRATCHED#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO 27/5, KARUR BYPASS ROAD, ANNAMALAI NAGAR, TIRUCHI; LM:THILLAINAGAR

City: Thillai Nagar S.O

Telephone Number : 8667674382

Mobile Number : 9944288028

Observation text: Cabinet damaged in washer Top 150 dealer policy - Carton box attached Marine insurance mail shared

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.