

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/107786 dated 24/08/2023 has been generated in reference to Service order No. 315710 dated 10/08/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02943/RT EONVIBE 346B HCIT ST RH

Replacement Product Code : 52141501SD02943 RT EONVIBE 346B HCIT ST RH

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02943 RT EONVIBE 346B HCIT ST RH

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202943FR00321

Invoice No : 11132442

Invoice Date : 04/08/2023

DOP : 04/08/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : MDoor,SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL REAR BOTTOM BUKCLING#APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO:1163,EAST MAIN STREET, NAZEER TOWER; OLD BUS STAND THANJAVUR,

City: THANJAVUR H.O

Telephone Number : 236231

Mobile Number : 9940112571

Observation text: Main door and side panel dent-MARINE INSURANCE Top 150 dealer policy - Carton box attached Appliance to be replaced

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES. TOP 150 VASANTH & CO.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

GIRISHAM

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.