

Dear NMS/SRINIR/ajayes

Sanction No. SS4/R/108243 dated 25/11/2023 has been generated in reference to Service order No. 350968 dated 23/11/2023.

Area : SS4 COIMBATORE

Model : 52141501SD02955/RT EONCRYSTAL 280B RI IC BK

Replacement Product Code : 52141501SD02955 RT EONCRYSTAL 280B RI IC BK

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02955 RT EONCRYSTAL 280B RI IC BK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230902955FR00091

Invoice No : 11137145

Invoice Date : 27/10/2023

DOP : 27/10/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 500 Labour Rs. 200 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - TABLE TOP#APPLIAN
CE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIYAS INVESTMENT PVT LMT GIRIYAS INVESTMENT PVT

Address : GIRIYAS INVESTMENT PVT LMT GIRIYAS INVESTMENT PVT LMT NO 469, SEK
KALAI ROAD, NEAR PERIYAR SELAI, KARAIKUDU,

City: Kallukatti S.O

Telephone Number : 8939517222

Mobile Number : 9042538596

Observation text: Side panel and table top damaged Top 150 dealer policy

Appliance to be replaced

Approval remark: FF-SIDE PANEL DAMAGED- TRANSIT/HANDLING DAMAGES. NOT REPAIR
ABLE.

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.