

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108647 dated 31/01/2024 has been generated in reference to Service order No. 373556 dated 29/01/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02954/RT EONCRYSTAL 280B RI OB

Replacement Product Code : 52141501SD02954 RT EONCRYSTAL 280B RI OB

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02954 RT EONCRYSTAL 280B RI OB

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230802954FR00219

Invoice No : 11134001

Invoice Date : 25/08/2023

DOP : 25/08/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 300 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top\_Dealer\_Trade\_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & GO VASANTH & CO

Address : VASANTH & GO VASANTH & CO NO 66; MODHILAL ST; KUMBAKONAM;

City: Kumbakonam City

Telephone Number : 7823921584

Mobile Number : 9940112558

Observation text: Side panel corner dent Top 150 dealer policy Appliance to be replaced

Approval remark: FF-SIDE PANEL DAMAGED- TRANSIT/HANDLING DAMAGES. NOT REPAIRABLE.

Sanction text: Top 150 dealer damaged policy case

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.