

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108705 dated 10/02/2024 has been generated in reference to Service order No. 377624 dated 10/02/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02929/RT EONALPHA 270B RI AR BL

Replacement Product Code : 52141501SD02929 RT EONALPHA 270B RI AR BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02929 RT EONALPHA 270B RI AR BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231002929FR00545

Invoice No : 11140510

Invoice Date : 11/01/2024

DOP : 11/01/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top\_Dealer\_Trade\_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO:1163,EAST MAIN STREET, NAZEER TOWER; OLD BUS STAND THANJAVUR,

City: THANJAVUR H.O

Telephone Number : 236231

Mobile Number : 9940112571

Observation text: Side panel Dent Top 150 dealer policy Appliance to be replaced

Approval remark: SIDE PANEL DENT-TRANSIT/HANDLING DAMAGES.

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.