

Dear KHANGAN/ADHI

Sanction No. SS4/R/108786 dated 24/02/2024 has been generated in reference to Service order No. 381138 dated 21/02/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03151/RD EDGE 205A THF GL WN

Replacement Product Code : 52141501SD03151 RD EDGE 205A THF GL WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03151 RD EDGE 205A THF GL WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240103151DR04037

Invoice No : 11006056

Invoice Date : 17/02/2024

DOP : 17/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : SEALED SYSTEM#GAS LEAK - DRIER SEALING#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : LUCKY STAR HOME LUCKY STAR HOME

Address : LUCKY STAR HOME LUCKY STAR HOME NO 13 SAPANI KOVILL ST ; CHEN CHATEY KULLAM ; TALLAKULAM ;

City: TALLAKULAM H O

Telephone Number : 9629609265

Mobile Number : 9629599265

Observation text: Capillary drier joint broken, Repair not allowed Pls apprc from FG as per dlr policy, Stk avl DOP: 17.02.24

Approval remark: CAPILLARY DRIER JOINT BROKEN REPAIR IS NOT ACCEPTABLE DOP 17TH FEB

Sanction text: CAPILLARY DRIER JOINT BROKEN

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.