

Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/108853 dated 04/03/2024 has been generated in reference to Service order No. 384054 dated 01/03/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02868/RD EMARVEL 207C THF FU WN

Replacement Product Code : 52141501SD02868 RD EMARVEL 207C THF FU WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02868 RD EMARVEL 207C THF FU WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202868DR02342

Invoice No : 11133314

Invoice Date : 17/08/2023

DOP : 17/08/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : SidePanel

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 300 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top_Dealer_Trade_policy

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - TABLE TOP#APPLIAN
CE TO BE REPLACED

PRA submitted by : Marudhudurai R

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & GO VASANTH & CO

Address : VASANTH & GO VASANTH & CO NO 66; MODHILAL ST; KUMBAKONAM;

City: Kumbakonam City

Telephone Number : 7823921584

Mobile Number : 9940112558

Observation text: Back panel damage Top 150 dealer policy Appliance to be replaced

Approval remark: back panel dent-transit/handling damages VASANTH & CO

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.