Dear KHANGAN/ADHI

Sanction No. SS4/R/108871 dated 12/03/2024 has been generated in reference to Service order No. 385646 dated 06/03/2024.

Area: SS4 COIMBATORE

Model: 52141501SD02392/RS EONVELVET 579 RFD PL ST

Replacement Product Code: 52141501SD02392 RS EONVELVET 579 RFD PL ST

Product Category : REFRIGERATOR

Defective Product Code: 52141501SD02392 RS EONVELVET 579 RFD PL ST Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 211002392SR00048

Invoice No : 16041098 Invoice Date : 05/02/2023

DOP: 27/05/2022

DEALER / CUSTOMER : DEALER
Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - DRIER_CONDENSOR JOINT#APPLIANCE TO BE

REPLACED

PRA submitted by : Marudhudurai R Customer / Dealer Code : 40000E

Customer / Dealer Name : MR KALIL. MR KALIL.

Address: MR KALIL. MR KALIL. NO -2 , NRJ ILLAM, NEW BUSTAN KUMBAKONAM,

City: BANADURAI Telephone Number:

Mobile Number: 8668112505

Observation text: GAs leak in heatingcoil - City SPD case Dealer replaced to customer on approval Appliance to be replaced

Approval remark: GAS LEAK ESCALATED CASE CUST CALL DATE 20/1/24 CUST DOF

5/2/23- BILL ATTACHED

Sanction text: gas leak problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective servic e executive.