Dear KHANGAN/ADHI/ajayes

Sanction No. SS4/R/109156 dated 30/04/2024 has been generated in reference to Service order No. 400713 dated 22/04/2024. Area : SS4 COIMBATORE Model : 52141501SD03179/RD EDGEPRO 255C TAF MN BL Replacement Product Code : 52141501SD03179 RD EDGEPRO 255C TAF MN BL Product Category : REFRIGERATOR Defective Product Code : 52141501SD03179 RD EDGEPRO 255C TAF MN BL Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240303179DR00193RZ Invoice No : 11143955 Invoice Date : 10/03/2024 DOP : 10/03/2024 DEALER / CUSTOMER : DEALER Damage/Defective : Damaged Transit from Mfg Plant / Bhiwandi to Branch Damage Happened During : Damaged Part(Only For Appl) : Cabinet Accountable By : Transporter Estimate Cost To Repair : Spares Rs. 1000 Labour Rs. 200 (Includes gas chargin q, if any) Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED PRA submitted by : ABISHEGK.R Customer / Dealer Code : 40000E Customer / Dealer Name : VASANTH & CO VASANTH & CO Address : VASANTH & CO VASANTH & CO NO:600, AMUTHAM PLAZA, SALEM RD, NAMAKK AL. City: NAMAKKAL H O Telephone Number : 8608948832 Mobile Number : 8939690051 Observation text: DAMAGED CASE, DEALER STOCKSET COMPLAINT.CABINET BOTTOM DEN T AND DAMAGED. STOCK AVAILABLE FOR RC PLEASE APPROVE THE SAME SIR Approval remark: SIDE PANEL BUCKLING- TRANSIT/HANDLING DAMAGES VASANTH & CO Sanction text: cabinet damaged in the machine Kindly take necessary action. ADHI Note to commercial team -- In case of any deviation (to actual machine) to above details , than abo

ve sanction no. stands void.
 - If any alteration required in above details than this document needs to be
regenerated (pdf format) through smartnet system. Contact respective servic
e executive.