Dear KHANGAN/ADHI Sanction No. SS4/R/109205 dated 17/05/2024 has been generated in reference to Service order No. 401198 dated 23/04/2024. COIMBATORE Area : SS4 Model: 52141501SD02928/RT EONALPHA 270B RI JD PR Replacement Product Code : 52141501SD02929 RT EONALPHA 270B RI AR BL Product Category : REFRIGERATOR Defective Product Code: 52141501SD02928 RT EONALPHA 270B RI JD PR Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202928FR01020 Invoice No : 350302270 Invoice Date : 15/11/2023 DOP : 15/11/2023 DEALER / CUSTOMER : CUSTOMER Damage/Defective : Defective Nature Of Problem : Customer\_Expectations\_-\_Not\_allowing\_Repairs Job Code Desc : SEALED SYSTEM#GAS LEAK - UNABLE TO IDENTIFY#APPLIANCE TO BE RE PLACED PRA submitted by : ABISHEGK.R Customer / Dealer Code : 40000E Customer / Dealer Name : CHINNA SAMY Address: CHINNA SAMY KUPPANUR, SUKKAMPATTI, 1/64 E City: Achankuttapatti B.O Telephone Number: 8940618002 Mobile Number : 9894338994 Observation text: CUSTOMER CASE, DEFECTIVE COMPLAINT. SEADLED SYSTEM GAS LEAK & CUSTOMER NOT ALLOWED TECH TO REPAIR PLEASE APPROVE THE SAME SIR Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. Sanction text: gas leak problem in the machine Kindly take necessary action. ADHI Dear KHANGAN/ADHI Sanction No. SS4/R/109205 dated 17/05/2024 has been generated in reference to Service order No. 401198 dated 23/04/2024. Area: SS4 COIMBATORE Model: 52141501SD02928/RT EONALPHA 270B RI JD PR Replacement Product Code: 52141501SD02929 RT EONALPHA 270B RI AR BL Product Category : REFRIGERATOR Defective Product Code: 52141501SD02928 RT EONALPHA 270B RI JD PR Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230202928FR01020 Invoice No : 350302270 Invoice Date : 15/11/2023 DOP : 15/11/2023 DEALER / CUSTOMER : CUSTOMER Damage/Defective : Defective Nature Of Problem : Customer Expectations - Not allowing Repairs Job Code Desc : SEALED SYSTEM#GAS LEAK - UNABLE TO IDENTIFY#APPLIANCE TO BE RE PLACED PRA submitted by : ABISHEGK.R Customer / Dealer Code : 40000E Customer / Dealer Name : CHINNA SAMY Address : CHINNA SAMY KUPPANUR, SUKKAMPATTI, 1/64 E

City: Achankuttapatti B.O Telephone Number: 8940618002 Mobile Number: 9894338994

Observation text: CUSTOMER CASE, DEFECTIVE COMPLAINT. SEADLED SYSTEM GAS LEAK & CUSTOMER NOT ALLOWED TECH TO REPAIR PLEASE APPROVE THE SAME SIR

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR.

Sanction text: gas leak problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.