

Dear KHANGAN/ADHI

Sanction No. SS4/A/101038 dated 18/05/2024 has been generated in reference to Service order No. 180999 dated 09/05/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01378/SIC 18VTC3 WYB TK

\*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01378 SIC 18VTC3 WYB TK

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240400098SA02324IZ

Invoice No : 11146716

Invoice Date : 27/04/2024

DOP : 27/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO: 66, MODHILAL STREET, KOMBAKONAM, THANJAVUR, LM: ANJANEYAR TEMPLE,

City: Kombakonam

Telephone Number : 9940112558

Mobile Number : 9940112558

Observation text: Compressor Gas leak - sealed system 06.05 cus dop Dealer replaced to customer on approval SRN due to stock unavailability

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR . REPLACED THRU DEALER.

Sanction text: gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.