

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101106 dated 10/06/2024 has been generated in reference to Service order No. 184880 dated 03/06/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01369/DSS 18PI3R32 WWP

Replacement Product Code : 40101701SD01369 DSS 18PI3R32 WWP

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01369 DSS 18PI3R32 WWP

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240301369SA04593

Invoice No : 16056553

Invoice Date : 29/03/2024

DOP : 29/03/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 240301369SA10344

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : COMPRESSOR#POOR PUMPING#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : DPR DIGITAL WORLD DPR DIGITAL WORLD

Address : DPR DIGITAL WORLD DPR DIGITAL WORLD NO:75 SHANMUGANAR STREET JEEN

A ROAD MAIN BAZAR TIRUPATTUR

City: Tirupattur Bazar

Telephone Number : 9443686127

Mobile Number : 9443686127

Observation text: CUSTOMER CASE- COMPRESSOR POOR PUMPING DEALER REPLACED TO CUSTOMER. STOCK AVAILABLE FOR RC. PLEASE APPROVE SIR-. CUS DOP-06/04/24

Approval remark: COMPRESSOR POOR PUMPING-CUST CASE-APR 24 DOP REPLACED THRU DEALER.

Sanction text: compressor problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.