

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/R/109316 dated 01/06/2024 has been generated in reference to Service order No. 407509 dated 12/05/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02975/RT EONVALOR 280B RCIT JD PR

Replacement Product Code : 52141501SD02975 RT EONVALOR 280B RCIT JD PR

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02975 RT EONVALOR 280B RCIT JD PR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230102975FR00061

Invoice No : 11137351

Invoice Date : 03/11/2023

DOP : 03/11/2023

DEALER / CUSTOMER : CUSTOMER

Damage/Defective : Defective

Nature Of Problem : Repeat\_Failure

Job Code Desc : COMPRESSOR#JAMMED TRIP / HOT#APPLIANCE TO BE REPLACED

PRA submitted by : Hiteshwaran G

Customer / Dealer Code : 40000E

Customer / Dealer Name : MURUGESAN MURUGESAN

Address : MURUGESAN MURUGESAN 10/33 NEW PLOT A NNA NAGAR BACK SIDE Tiruchi rappa lli Fort SO A

City: Clock Tower

Telephone Number :

Mobile Number : 9750388778

Observation text: Replcd comprsr again prblm gas chrgng 2 tims done Cus not allowing to repair dop 03.11.2023 Appliance to be replaced

Approval remark: GAS LEAK - CUST CASE- NOT ACCEPTING REPAIR. REPEAT

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.