## Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/W/102284 dated 27/06/2024 has been generated in reference to Service order No. 420445 dated 20/06/2024.

Area: SS4 COIMBATORE

Model: 52141601SD00387/WTEON ADR 65 5.0 FDTN GPGR

Replacement Product Code : 52141601SD00387 WTEON ADR 65 5.0 FDTN GPGR

Product Category : WASHING MACHINE

Defective Product Code: 52141601SD00387 WTEON ADR 65 5.0 FDTN GPGR Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 230600387FW01726

Invoice No : 11133103 Invoice Date : 14/08/2023

DOP: 14/08/2023

DEALER / CUSTOMER : DEALER Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 600 Labour Rs. 300 (Includes gas charging , if any)

Nature Of Problem : Top\_Dealer\_Trade\_policy

Job Code Desc: CABINET#CABINET - BROKEN / SCRATCHY - TRANSIT DAMAGE#APPLIANCE TO BE REPLACED

PRA submitted by : Hiteshwaran G Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address: VASANTH & CO VASANTH & CO NO 27/5, KARUR BYPASS ROAD, ANNAMALAI

NAGAR; TIRUCHI; LM:THILLAINAGAR

City: Thillai Nagar S.O Telephone Number: 8667674382

Mobile Number : 9944288028

Observation text: Cabinet bottom damage near leg Dealer wants replacement

Appliance to be replaced

Approval remark: CABINET DAMAGED FROM THE BASE-TRANSIT/HANDLING DAMAGES. NO

T FEASIBLE TO REPAIR.

Sanction text: Cabinet damaged in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.