## Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/D/100252 dated 02/07/2024 has been generated in reference to Service order No. 421937 dated 24/06/2024.

Area: SS4 COIMBATORE

Model: 24131601SD00066/DH EPENTA 325C 31CMFH2 M RW

Replacement Product Code: 24131601SD00066 DH EPENTA 325C 31CMFH2 M RW

Product Category : DEEP FREEZER

Defective Product Code: 24131601SD00066 DH EPENTA 325C 31CMFH2 M RW Cabinet No(For Appl) and SO/RPL/Invoice No(For Others): 221100066CR00373

Invoice No : 11126875 Invoice Date : 28/05/2023

DOP: 28/05/2023

DEALER / CUSTOMER : CUSTOMER Damage/Defective : Defective

Nature Of Problem : Functional\_Defect\_-\_Not\_repairable

Job Code Desc : SEALED SYSTEM#GAS LEAK - SUCTION JOINT#APPLIANCE TO BE REPLACE

D

PRA submitted by : DEEPAK K
Customer / Dealer Code : 40000E
Customer / Dealer Name : SELVI SELVI

Address : SELVI SELVI NO : 7/12 ; TELEPHONE CLY ; UDHAYAM NAGAR ; KOTTAIYU

R ;

City: Kottaiyur S.O

Telephone Number: 9524665194 Mobile Number: 9524665194

Observation text: DAMAGE CREATED IN THE EVA COIL AND AL COIL Al COIL CANT BE WELDED SO NEED TO PROCESS RC PREVIOUS CALL - 412313 BOOKED IB S4S. PLEASE

Approval remark: EVAP COIL LEAK- CUST CASE PREVIOUS CALL NUMBER IS MENTIONED WHICH IS BOOKED EARLIER FOR THE SAME REASONS

Sanction text: evaporator problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.