## Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101207 dated 15/07/2024 has been generated in reference to Service order No. 188520 dated 09/07/2024.

Area: SS4 COIMBATORE

Model: 40101701SD01216/SIC 18ITC5-WWR \*\*\*\*\* SRN \*\*\*\*\*

Product Category : AIR CONDITIONER

Defective Product Code: 40101701SD01216 SIC 18ITC5-WWR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 231201216SA06253

Invoice No : 11140558
Invoice Date : 11/01/2024

DOP : 11/01/2024

DEALER / CUSTOMER : DEALER
Damage/Defective : Defective
PRA submitted by : ABISHEGK.R
Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH &CO VASANTH &CO

Address: VASANTH &CO VASANTH &CO NO: 32/134 PRAJATHINAM ROAD CHINNAPPA KAR

UR

City: Karur H.O

Telephone Number : 24236623 Mobile Number : 9940112581

Observation text: VASANTH & CO CASE- INDOOR PCB DEFECT & NOT WORKING NO STOC

K FOR RC & SRN DONE. PLEASE APPROVE THE SAME SIR.

Approval remark: INDOOR PCB DEFECT-DEALER STOCK SET CASE

Sanction text: PCB problem in the machine

Kindly take necessary action. ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective servic e executive.