

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101283 dated 03/09/2024 has been generated in reference to Service order No. 692827 dated 17/08/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240101277SA06249ZT

Invoice No : 11143067

Invoice Date : 27/02/2024

DOP : 27/02/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : AVUDAIAPPAN S

Customer / Dealer Code : 40000E

Customer / Dealer Name : FAMINA ELECTRONICS FAMINA ELECTRONICS

Address : FAMINA ELECTRONICS FAMINA ELECTRONICS 508/510 BIG BAZZER STREET F

AMINA COMPLEX DHARAPURAM TIRUPUR

City: DHARAPURAM H O

Telephone Number : 6382405009

Mobile Number : 9443732410

Observation text: COMPRESSOR JAMMED- defective DEALER WANTS REPLACEMENT DOP

27.02.2024 SRN DUE TO STOCK UNAVAILABILITY

Approval remark: COMPRESSOR DEFECT-DEALER STOCK SET CASE.

Sanction text: compressor problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.