

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101299 dated 16/09/2024 has been generated in reference to Service order No. 695439 dated 11/09/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

***** SRN *****

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 230901277SA00105

Invoice No : 11120626

Invoice Date : 27/12/2023

DOP : 27/12/2023

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

PRA submitted by : DEEPAK K

Customer / Dealer Code : 40000E

Customer / Dealer Name : SRI LAKSHMI FURNITURE MART SRILAKSHMI FURNITURE MA

Address : SRI LAKSHMI FURNITURE MART SRILAKSHMI FURNITURE MART 34B NEW STREE

T MANNARGUDI

City: Kumbakonam Bazar

Telephone Number : 9894121010

Mobile Number : 9894121010

Observation text: GAS LEAK IN THE CONDENSOR COIL CUST CREATED ISSUE IN DEALER POINT SO DEALER RC TO THEM NOW SRN REQ BY ASP KINDLY APPROVE | DOP-12-4-24

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. CUST NOT ACCEPTING REPAIR . REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.