

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/R/110379 dated 12/10/2024 has been generated in reference to Service order No. 324681 dated 04/10/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03546/RD ERIOPLS 205C THF SE BL

Replacement Product Code : 52141501SD03546 RD ERIOPLS 205C THF SE BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03546 RD ERIOPLS 205C THF SE BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240503546DR01968

Invoice No : 11147875

Invoice Date : 24/05/2024

DOP : 24/05/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - DRIER_CAPILLARY JOINT#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : KSM JEWELS & METALS KSM JEWELS & METALS

Address : KSM JEWELS & METALS KSM JEWELS & METALS 106/166;MUNSHEEP COURT ROAD;THIRUMANGALAM

City: TIRUMANGALAM S.O

Telephone Number : 9965288112

Mobile Number : 9843340508

Observation text: Gas leak from drier joint, Cust ret, Inv attached Pls appr replacement from FG, Stk avl Cust DOP: 18.09.24, Call no: 321202, dt: 23.09.24

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.

ADHI

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/R/110379 dated 12/10/2024 has been generated in reference to Service order No. 324681 dated 04/10/2024.

Area : SS4 COIMBATORE

Model : 52141501SD03546/RD ERIOPLS 205C THF SE BL

Replacement Product Code : 52141501SD03546 RD ERIOPLS 205C THF SE BL

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD03546 RD ERIOPLS 205C THF SE BL

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240503546DR01968

Invoice No : 11147875

Invoice Date : 24/05/2024

DOP : 24/05/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

Nature Of Problem : Dealer_replaced_to_customer_approved_by_Service

Job Code Desc : SEALED SYSTEM#GAS LEAK - DRIER_CAPILLARY JOINT#APPLIANCE TO BE REPLACED

PRA submitted by : Kumaraselvan R

Customer / Dealer Code : 40000E

Customer / Dealer Name : KSM JEWELS & METALS KSM JEWELS & METALS

Address : KSM JEWELS & METALS KSM JEWELS & METALS 106/166;MUNSHEEP COURT ROAD;THIRUMANGALAM

City: TIRUMANGALAM S.O

Telephone Number : 9965288112

Mobile Number : 9843340508

Observation text: Gas leak from drier joint, Cust ret, Inv attached Pls appr replacement from FG, Stk avl Cust DOP: 18.09.24, Call no: 321202, dt: 23.09.24

Approval remark: GAS LEAK - CUST CASE-NEW MACHINE. REPLACED THRU DEALER.

Sanction text: Gas leak problem in the machine

Kindly take necessary action.
ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.
- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.