

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/110532 dated 11/11/2024 has been generated in reference to Service order No. 337921 dated 08/11/2024.

Area : SS4 COIMBATORE

Model : 52141501SD02548/RD EDGESX 236C 33 TAI FL WN

Replacement Product Code : 52141501SD02845 RD EDGESX 236C TAI FL WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02548 RD EDGESX 236C 33 TAI FL WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 221002548DR01172

Invoice No : U24009080

Invoice Date : 26/08/2024

DOP : 26/08/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Mfg Plant / Bhiwandi to Branch

Damaged Part(Only For Appl) : Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 1000 Labour Rs. 200 (Includes gas charging, if any)

Nature Of Problem : Dealer\_Expectations\_-\_Not\_allowing\_Repairs

Job Code Desc : CABINET2#CABINET - DAMAGED/DENTS & SCRATCHES#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : AB COOLING SOLUTIONS AB COOLING SOLUTIONS

Address : AB COOLING SOLUTIONS AB COOLING SOLUTIONS NO10 KRISHNA SWAMI ST, MUNILISPLE COLONY ; VEERAPPANCHATRAM, ERODE

City: Veerappanchatram S.O

Telephone Number : 8610131309

Mobile Number : 9842241641

Observation text: DAMAGED CASE DEALER STOCKSET CASE. CABINET BOTTOM DENT AND DAMAGED. PLEASE APPROVE FOR REPLACEMENT SIR.

Approval remark: cabinet damaged from the bottom center and SIDE PANEL DENT AND S WELL transit/handling damages

Sanction text: cabinet damaged from the bottom center and SIDE PANEL DENT AND S WELL transit/handling damages

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation ( to actual machine ) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated ( pdf format ) through smartnet system. Contact respective service executive.