

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/W/102455 dated 22/10/2024 has been generated in reference to Service order No. 327021 dated 12/10/2024.

Area : SS4 COIMBATORE

Model : 52141601SD00298/WSEEDGE 80 5.0 TB3 M LVDR

Replacement Product Code : 52141601SD00298 WSEEDGE 80 5.0 TB3 M LVDR

Product Category : WASHING MACHINE

Defective Product Code : 52141601SD00298 WSEEDGE 80 5.0 TB3 M LVDR

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240400298SW00919IZ

Invoice No : 11146538

Invoice Date : 25/04/2024

DOP : 25/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) :

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 2500 Labour Rs. 550 (Includes gas charging, if any)

Nature Of Problem : Not_repairable

Job Code Desc : CABINET#CABINET - BROKEN / SCRATCHY - TRANSIT DAMAGE#APPLIANCE TO BE REPLACED

PRA submitted by : SURYA VEL M D

Customer / Dealer Code : 40000E

Customer / Dealer Name : GIRIYAS INVESTMENT PVT LMT GIRIYAS INVESTMENT PVT

Address : GIRIYAS INVESTMENT PVT LMT GIRIYAS INVESTMENT PVT LMT NO 469, SEK KALAI ROAD, NEAR PERIYAR SELAI, KARAIKUDU

City: Kallukatti S.O

Telephone Number : 6385896386

Mobile Number : 8939516222

Observation text: CABINET BROKEN AND SCRATCHED FOUND

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES.

GIRIAS

Sanction text: cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.