

Dear KHANGAN/NANDHINIS.LO

Sanction No. SS4/A/101386 dated 14/12/2024 has been generated in reference to Service order No. 723304 dated 09/12/2024.

Area : SS4 COIMBATORE

Model : 40101701SD01277/SIC 18TTC3 GWD SPLIT

Replacement Product Code : 40101701SD01442 SIC 18TTC3 WYQ SPLIT

Product Category : AIR CONDITIONER

Defective Product Code : 40101701SD01277 SIC 18TTC3 GWD SPLIT

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240401277SA01999WJ

Invoice No : 11146147

Invoice Date : 17/04/2024

DOP : 17/04/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Defective

AC UNIT : IDU-ODU

ODU No : 240301277SA12635LZ

Nature Of Problem : Dealer_Expectations_-_Not_allowing_Repairs

Job Code Desc : EVAPORATOR - COPPER#DAMAGED#APPLIANCE TO BE REPLACED

PRA submitted by : ABISHEGK.R

Customer / Dealer Code : 40000E

Customer / Dealer Name : MANI TV CENTRE MANI TV CENTRE

Address : MANI TV CENTRE MANI TV CENTRE prashan sakthi nagar attur undefined Gandhi Road1, Udayarpalayam, Attur, Tamil Nadu 636102, India

City: Attur Salem

Telephone Number : 9843794229

Mobile Number : 9965212120

Observation text: DEALER STOCK SET CASE-EVAPORATOR COIL DAMAGED DEALER EXPECTING REPLACEMENT FOR THE SAME. PLEASE APPROVE THE SAME SIR

Approval remark: EVAPORATOR COIL DAMAGED TRANSIT/HANDLING DAMAGES.

Sanction text: Evaporator problem in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.