

Dear KHANGAN/NANDHINIS.LO/ajayes

Sanction No. SS4/R/110851 dated 07/01/2025 has been generated in reference to Service order No. 355019 dated 04/01/2025.

Area : SS4 COIMBATORE

Model : 52141501SD02868/RD EMARVEL 207C THF FU WN

Replacement Product Code : 52141501SD02868 RD EMARVEL 207C THF FU WN

Product Category : REFRIGERATOR

Defective Product Code : 52141501SD02868 RD EMARVEL 207C THF FU WN

Cabinet No(For Appl) and SO/RPL/Invoice No(For Others) : 240802868DR02896ZR

Invoice No : 11154219

Invoice Date : 18/09/2024

DOP : 18/09/2024

DEALER / CUSTOMER : DEALER

Damage/Defective : Damaged

Damage Happened During : Transit from Branch to Dealer / Distributor / Cust

Damaged Part(Only For Appl) : MDoor,Cabinet

Accountable By : Transporter

Estimate Cost To Repair : Spares Rs. 1000 Labour Rs. 200 (Includes gas charging, if any)

Nature Of Problem : Not_repairable

Job Code Desc : CABINET#CABINET - DAMAGED/DENTS & SCRATCHES - SIDE PANEL DENT# APPLIANCE TO BE REPLACED

PRA submitted by : KAMAL T

Customer / Dealer Code : 40000E

Customer / Dealer Name : VASANTH & CO VASANTH & CO

Address : VASANTH & CO VASANTH & CO NO 1 NORTH MAIN ROAD,NEAR THIYAGARAJA TEMPLE ,TIRUVARUR, TAMIL NADU NO 1 VAKUTHERU

City: Tiruvarur H.O

Telephone Number : 7823921590

Mobile Number : 7823921590

Observation text: CABINET DAMAGED, SIDE PANEL DENT&MAIN DOOR DENT. SR.NO & IMG ATTACHED. DOP : 18/09/24. KINDLY APPROVE.

Approval remark: CABINET DAMAGED -TRANSIT/HANDLING DAMAGES. VASANTH & CO

Sanction text: Cabinet damaged in the machine

Kindly take necessary action.

ADHI

Note to commercial team -

- In case of any deviation (to actual machine) to above details , than above sanction no. stands void.

- If any alteration required in above details than this document needs to be regenerated (pdf format) through smartnet system. Contact respective service executive.