

Packing Slip
(Annexure to Material Return)

Inspection Report No.: 3880003997W

From: Deeksha Agencies(FCDE0781) 1/79, Mangalanayakipuram,thiruthura TIRUTURAI PUNDI-TN 614703 TAMIL NADU India GSTIN:33FVEPP5478R1ZK				To: Havells India Limited Branch- Chennai (TN1) No.18, Koduvalli Village,Veppampattu Rd, Thiruvallur Taluk & District, Chennai Chennai 600055 GSTIN.: 33AAACH0351E1ZC CIN No.: L31900DL1983PLC016304			
Sr. No.	Material	Description	Desination Plant	Storage Location	Total	Packed	Carton No.
1.00	GSCELOLX0017	Motor - Aspro	1065	F800	1.000	1.000	1
2.00	GHWAPFTWH10	PURO NU 5S 10L SP FP-WH	1383	F800	1.000	1.000	2
3.00	GSSGCX0625	KALT 24L-MAIN MOTOR	2207	F800	1.000	1.000	3
4.00	GHPWGCXR015	Alai # WG Table Top 150 W	2456	F800	1.000	1.000	4
				Total	4.000	4.000	4

Inspected Cartons: 4 Inspection Date: 25.03.2025 Inspected By: 613599 Transport Name: GR No & Date:	Challan No. & Date: Customer Stamp & Signature
--	---

Note:- Challan cum GR detail entry is pending

Note:For Internal reference only, not for transit purpose